


# O-360-C1F - Main wear metals and Lead (Pb) in oil samples



**Note:**  
Fe and Pb are not to scale. Fe values are divided by 2 and Pb values are divided by 200.