



GARMIN[™]

Socata TBM850 G1000 Config Mode Screens

This guide will allow a Service Center to determine if unauthorized changes have been made in G1000 Configuration screens for the TBM850. If the G1000 system software version is 0719.01, and the screens do not match these shown, unauthorized changes may have been made. Contact Garmin Product Support for assistance if needed to reset the G1000 system.

This presentation is for reference only and does not replace any approved G1000 Service Literature instructions.